HISTORIC AMERICAN ENGINEERING RECORO

INOEX TO PHOTOGRAPHS

Thirty First St. Overflow Structure 31st St. Oenver County, Oenver, CO

HAER CO-18

Photographer: T.W. Graddy, April, 1978

- CO-18-1 OVERFLOW CHAMBER. VIEW IS NORTH (OOWNSTREAM). NOTE OELGANY SEWER ON RIGHT SIDE OF NEGATIVE AND OVERFLOW CHANNEL ON LEFT SIDE OF IMAGE.
- CO-18-2 OVERFLOW CHAMBER. VIEW IS SOUTH (UPSTREAM). NOTE DELGANY SEWER ON LEFT SIDE OF NEGATIVE.
- CO-18-3 OF ARCH FORMING THE BASE OF THE OOWNSTREAM (NORTH) MANHOLE.
- CO-18-4 GENERAL SETTING OF THIRTY FIRST STREET OVERFLOW STRUCTURE. VIEW IS NORTHEAST LOOKING TOWARDS OVERFLOW CHANNEL MOUTH.
- CO-TO-5 OETAIL OF ARCH INSIDE OVERFLOW CHAMBER ON THE SOUTH (UPSTREAM) ENO.
 NOTE OELGANY SEWER ON THE LEFT SIDE OF THE NEGATIVE.
- CO-10-6 EXTREME CLOSEUP OF ARCH AT THE UPSTREAM (SOUTH) END OF OVERFLOW CHAMBER.
- CO-10-7 EXTREME CLOSEUP OF JUNCTION POINT OF ARCHES AT THE OOWNSTREAM (NORTH) END OF OVERFLOW CHAMBER. THE ARCH LEADING INTO THE OELGANY SEWER IS JUST VISIBLE ON THE RIGHT SIDE OF THE NEGATIVE.
- CO-10-8 OVERFLOW CHANNEL MOUTH. VIEW IS NORTHEAST.
- CO-10-9 OVERFLOW CHANNEL MOUTH. VIEW IS SOUTHEAST.
- CO-10-10 OETAIL DRAWING OF CAPSTONE (NOW GONE) FOR OVERFLOW CHANNEL MOUTH.
- CO-TO-TT ORIGINAL PLAN FOR OVERFLOW CHANNEL MOUTH.
- CO-10-12 EXTENSION OF DELGANY SEWER, SHEET 2.
- CO-10-13 PLAN FOR WEIR COPING STONES. THESE ARE THE GRANITE STONES VISIBLE INSIDE THE OVERFLOW CHAMBER.
- CO-10-14 OFTAILED PLAN OF THIRTY FIRST STREET OVERFLOW STRUCTURE.
- CO-10-15 OVERALL PLAN WITH SECTIONS OF THIRTY FIRST STREET OVERFLOW STRUCTURE.
- CO-10-16 MAP OF EXTENSION OF OELGANY STREET PUBLIC SANITARY SEWER.
- CO-10-17 CROSS SECTION OF SEWER IN THIRTY FIRST STREET OVERFLOW STRUCTURE.
- CO-10-18 PLAN FOR PILING AND CROSS SECTION OF OUTLET 31st STREET OVERFLOW STRUCTURE.